Message Text

UNCLASSIFIED

PAGE 01 STATE 238959

64

ORIGIN USIA-09

INFO OCT-01 EUR-12 ISO-00 RSC-01 /023 R

66609

DRAFTED BY: USIA/ICS:O:RSBYRNES/ICS/X:GWUINN APPROVED BY: STATE/EUR/EX:JGEISEL PHONE USIA/ICS:HSCHNEIDMAN

ICS:WBDAVIS

ICS/XP:RUNDERSOOD EUR/EE/TDUNLOP PHONE ICS/X:WRIDGEWAY IEEC:PBROWN PHONE ICS/OL:LLEHTONEN INFO

----- 045329

P 310032Z OCT 74

FM SECSTATE WASHDC

TO AMEMBASSY BUCHAREST PRIORITY

UNCLAS STATE 238959

E.O. 11652: NA

TAGS:

SUBJ: PHOTOGRAPHY USA-DOME SKIN REPAIR

FOR NIGLIS

REF: BUCHAREST 4909-U

- 1. REQUEST NIGLIS ARRANGE FOR DOME TO REMAIN IN PLACE FOR URGENT REPAIRS.
- 2. REQUEST REX BARKANIC ARRANGE FOR ENGINEER HEIDWEGER REPAIR DOME SKIN SOONEST.
- 3. THE DETERIORATED POINTS AROUND BOTTOM OF SKIN WHERE TUBE 26 IS INSERTED INTO SLEEVE MUST BE REPAIRED.
- 4. NEW FABRIC, SAME QUALITY AS SKIN SHOULD BE GLUED ONTO BOTTOM OF SLEEVE BEFORE TUBE 26 IS REMOVED. NEW FABRIC SHOULD BE UNCLASSIFIED

UNCLASSIFIED

PAGE 02 STATE 238959

INSTALLED FULL LENGTH OF EACH SLEEVE--FABRIC SHOULD BE 25CM

WI	DE.

- $5.\ TUBE\ 26\ CAN\ BE\ DISCONNECTED\ FROM\ DOME\ FRAME\ TO\ ALLOW\ FOR\ EASIER\ ACCESS.$
- 6. INFORM ICS TIME SCHEDULE AND ESTIMATE FOR REPAIRS.
- 7. IF CHAINS ARE RUSTY, SPRAY WITH ALUMINUM PAINT BEFORE LOWERING TENT. DO NOT CHANGE ANY CHAINS.
- $8.\ PACK$ SKIN CAREFULL AS NOTED STATE 231781-U SHIP TO VIENNA.
- 9. REQUEST REX PUT DOME INTO CONTAINERS.

VIENNA INFORMED. INGERSOLL

UNCLASSIFIED

NNN

Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED Concepts: NIGLIS, PHOTOGRAPHY

Control Number: n/a Copy: SINGLE Draft Date: 31 OCT 1974 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Case Number: n/a
Disposition Comment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:

Document Number: 1974STATE238959
Document Source: CORE
Document Unique ID: 00
Drafter: USIA/ICS:O:RSBYRNES/ICS/X:GWUINN

Enclosure: n/a Executive Order: N/A Errors: N/A Film Number: D740310-0554 From: STATE

Handling Restrictions: n/a

Image Path:

Legacy Key: link1974/newtext/t1974102/aaaaabjj.tel Line Count: 77

Locator: TEXT ON-LINE, ON MICROFILM

Office: ORIGIN USIA Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 2

Previous Channel Indicators: Previous Classification: n/a Previous Handling Restrictions: n/a Reference: BUCHAREST 4909-U Review Action: RELEASED, APPROVED Review Authority: golinofr

Review Comment: n/a Review Content Flags: Review Date: 19 APR 2002

Review Event:

Review Exemptions: n/a
Review History: RELEASED <19 APR 2002 by chappeld>; APPROVED <23 MAY 2002 by golinofr>

Review Markings:

Declassified/Released US Department of State EO Systematic Review 30 JUN 2005

Review Media Identifier: Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: PHOTOGRAPHY USA-DOME SKIN REPAIR FOR NIGLIS

TAGS: TECH To: BUCHAREST

Type: TE

Markings: Declassified/Released US Department of State EO Systematic Review 30 JUN 2005